




CR 100-1  
crimp




CR 100-2  
solder cup




CR 100-2E12  
solder cup




CR 100-2B  
solder cup




CR 100-2-05  
solder cup




CR 100-2-2.5  
solder cup




CR 100-3  
wire wrap




CR 100-4  
round post  
vacuum-sealed




CR 100-3V  
wire wrap  
vacuum-sealed




CR 100-3E12  
wire wrap



CR 100-3-05  
wire wrap  
vacuum-sealed



CR 100-3-25  
wire wrap  
vacuum-sealed



## Materials

Receptacle: Nickel-silver or Brass, gold plated

## Hole size for receptacle

Drills for press ring as a stop:

$\phi 1,67 - \phi 1,68$

Drills for press ring insert:

$\phi 1,70 - \phi 1,75$

