



Tools

Probes and receptacles extractor tools



CT xxx IE

Extractor tool suitable for all probes with head.



CT E xxx

Screw the tool into the receptacle and pull out. With this extraction tool receptacles can be removed quickly, avoiding risks of damaging the support. This tool is especially useful to remove broken receptacles or in case the receptacle cannot be pushed out from the back.

Ordering example:

Series	
CT E	CR 113
Probe type or Receptacle type	